

## SERVICE BULLETIN

## **KODAK X-OMAT Processor**

Eastman Kodak Company/Customer & Technical Services/Health Sciences Markets Division/Rochester, New York 14650

**SERVICE BULLETIN NO. 199** 

August 1994

Kodak X-Omatic Identification Camera, Models 4 and 4L Kodak X-Omatic Identification Camera, Models X-1 and X-1-L Kodak X-Omatic Identification Camera, Models 2 and 2-L Kodak Min-R and Min-R L Identification Cameras

## A New TOOL Is Available for the Kodak Identification Cameras

An ACTUATOR PIN ALIGNMENT TOOL, Part No. 1C0071, is now available. The tool comes in a pouch and "How to Use" instructions are included.

The tool is used to adjust the ACTUATOR PIN in the above listed ID cameras after installing a new ACTUATOR ASSEMBLY or a new STAY ASSEMBLY.

Using this tool with the instructions extends the life of the ACTUATOR and will make it easier to work on the ID cameras.

For more information, please contact:

Eastman Kodak Company Imaging Service Center Health Sciences Division 100 Carlson Road Rochester, New York 14653-9013 (716) 724-1789

svcbul\_199.txt N-911

Kodak, X-Omatic and Min-R are trademarks.

Health Sciences Division Kodak